

ATTESTATION



This is to confirm that

Dongguan Dongdian Testing Service Co., Ltd. No. 17, Zongbu Road, 2, Songshan Lake Sci&Tech, Industry Park, Dongguan City 523808, Guangdong Province, People's Republic of China

has been accepted by

TÜV SÜD China Guangzhou Branch – 5/F, Communication Building .163 Pingyun rd. Huangpu Ave. West, Guangzhou, P. R. China (On behalf of TÜV SÜD China Shenzhen Branch & TÜV SÜD Hong Kong Ltd.)

for cooperating in on-site witness projects according to the following standards:

IEC/EN 60950-1, IEC/EN 60065, IEC/EN 61558-1, IEC/EN 61558-2-6, IEC/EN 61558-2-7, IEC/EN 61558-2-16, IEC/EN 61347-1, IEC/EN 61347-2-13, IEC/EN 60598-1, IEC/EN 62560, EN 55013, CISPR 13, EN 55014-1, CISPR 14-1, EN 55014-2, CISPR 14-2, EN 55015, CISPR 15, EN 55022, CISPR 22, EN 55024, CISPR 24, IEC/EN 61547, IEC/EN 61000-3-2. IEC/EN 61000-3-3

This document states that the above named company is included in the TÜV SÜD PRODUCT SERVICE GROUP (TÜV SÜD) Listing of Recognized Laboratories and is qualified in compliance with the TÜV SÜD External Test Laboratory (ETL) program for the mutually agreed product categories and/ or standards.

As far as the testing facilities meet the relevant requirements of this program and the tests of the projects are conducted under the supervision and witness of the engineer(s) of TÜV SÜD China Guangzhou Branch or other 2 TÜV SÜD offices in South China Region, the test results can be used as a basis for a TÜV SÜD certification.

Attestation No.: **Expiration Date:** SCN1092

2014-01-05

TÜV SÜD China – South Region

Robert Ostendorf

Date of Issuance: 2013-01-05



*TÜV SÜD makes no representations or warranties, express or implied, regarding any aspect of this Laboratory's business or services or that this Laboratory's services will achieve any specific results in any TÜV SÜD investigation. TÜV SÜD does not assume or undertake to discharge any liability of this Laboratory or any other party. TÜV SÜD assumes no liability which may result directly or indirectly from assessment or Certification of this Laboratory, the conduct or a failure to conduct inspections, incorrect Certification, nonconformity of failure to discover nonconformity with Program Requirements, cancellation of this Attestation or withdrawal of this Laboratory Survivals of Results of this Attestation. This Laboratory survivals of Results of the Results of this Attestation. This Laboratory bears sole responsibility for its provision of services.